

Application Listing  
Porsche  
2/17/2011.Vdm



Make	Model	Chassis	Year	Applications				
				Front P/N	Front MSRP	Rear P/N	Rear MSRP	
Porsche	911 Series	3.3 SC turbo/turbo look	930	1979-89	7326- D608	\$ 119.50	7326- D608	\$ 119.50
		C2 3.6	964	1990-91	7326- D608	\$ 119.50	NA	
		C2/C4/C4S 3.6	964	1992-94	7326- D608	\$ 119.50	7326- D608	\$ 119.50
		C2 3.6 Turbo Look	964	1991-94	7327- D609	\$ 128.50	7326- D608	\$ 119.50
		Carrera RS 3.6	964	1991-94	7327- D609	\$ 128.50	7326- D608	\$ 119.50
		3.3 Turbo/Turbo S	965	1991-92	7327- D609	\$ 128.50	7326- D608	\$ 119.50
		C2/C4 3.6	993	1995-98	7327- D609	\$ 128.50	7326- D608	\$ 119.50
		C2/C4	996	1999-05	7798- D917*	\$ 149.50	7646- D738*	\$ 128.50
		C4S-4+Turbo Look w/ iron discs	996	2001-05	7797- D916*	\$ 157.50	7798- D917*	\$ 149.50
		Turbo w/ iron discs	996	2001-05	7797- D916*	\$ 157.50	7798- D917*	\$ 149.50
		C4S-4 Turbo Look w/ ceramic orig.	996	2001-05	7892- D991	\$ 189.50	7798- D917*	\$ 149.50
		Turbo/GT2 w/ ceramic discs orig.	996	2001-05	7892- D991	\$ 189.50	7798- D917*	\$ 149.50
		GT3 w/ iron or ceramic	996	2004-05	7892- D991	\$ 189.50	7798- D917*	\$ 149.50
		C2/C4	997	2005-07	7798- D917*	\$ 149.56	7646- D738*	\$ 128.50
		C2S/C4S Turbo Look w/ iron	997	2005-07	7797- D916*	\$ 157.50	7798- D917*	\$ 149.50
		C2S/C4S TurboLook w/ ceramic orig.	997	2005-07	7892- D991	\$ 189.50	7798- D917*	\$ 149.50
		Turbo/GT2/GT3 w/ iron	997	2006	7797- D916*	\$ 157.50	7798- D917*	\$ 149.50
		Turbo/GT2/GT3 w/ceramic orig.	997	2006	7892- D991	\$ 189.50	7643- D917*	\$ 149.50
		Turbo w/ iron or ceramic discs	997	2007	7892- D991	\$ 189.50	8416- D1300	\$ 149.50
		GT3 w/iron or ceramic discs	997	2007	7892- D991	\$ 189.50	8416- D1300	\$ 149.50
Boxster	Boxster S	986	1997-00	7643- D776*	\$ 107.50	7646- D738*	\$ 128.50	
	Boxster S	986	2001-04	7798- D917*	\$ 149.50	7646- D738*	\$ 128.50	
	Boxster S w/ iron discs	987	2005-	7798- D917*	\$ 149.50	7646- D738*	\$ 128.50	
	Boxster S w/ ceramic discs orig.	987	2005-	7892- D991	\$ 189.50	7798- D917*	\$ 149.50	
	Boxster (non-S)	986	1997-04	7606- D737*	\$ 128.50	7646- D738*	\$ 128.50	
	Boxster (non-S)	987	2005-	7606- D737*	\$ 128.50	7646- D738*	\$ 128.50	
Cayman	Cayman/S w/ iron discs	987	2006-08	7798- D917*	\$ 149.50	7646- D738*	\$ 128.50	
	Cayman/S w/ ceramic discs	987	2006-08	7892- D991	\$ 189.50	7798- D917*	\$ 149.50	
928 Series	928, 928S, S4, GT,GTS	928	1986-91	7327- D609	\$ 128.50	7326- D608	\$ 119.50	
	928 w/4.7 engine	928	1981-85	7285- D395	\$ 117.95	NA		
944 Series	944 S2 (w/o Sport)	944	1989-91	7326- D608	\$ 119.50	7326- D608	\$ 119.50	
	944 S2 (w/sport Koni's)	944	1989-91	7327- D609	\$ 128.50	7326- D608	\$ 119.50	
	944Turbo	951	1985-88	7326- D608	\$ 119.50	7326- D608	\$ 119.50	
	944 Turbo S	951	1988-89	7327- D609	\$ 128.50	7326- D608	\$ 119.50	
968 Series	968 (w/o Sport)	968	1992-95	7326- D608	\$ 119.50	7326- D608	\$ 119.50	
	968 (w/Sport )	968	1992-95	7327- D609	\$ 128.50	7326- D608	\$ 119.50	

Notes: D776 = D917 w/o counterweights  
D993 = D917 w/snap-in Wear Sensor (Option from 2003 on)  
\* = Linings Edge Drilled for Wear Sensor